


HORIZONTAL MARCELLUS WELL ACTIVITY IN OHIO



EXPLANATION

Horizontal well status as of 5/2/2015

- ◆ PERMITTED-(Permitted; Not Drilled; Canceled) (15)
- DRILLED-(Drilling; Well Drilled) (13)
- PRODUCING-(Producing; Plugged Back) (14)
- INACTIVE-(Drilled Inactive; Shut in) (1)
- Lost Hole or Final Restoration (0)
- Dry and Abandoned (0)
- Plugged and Abandoned (0)

OPERATOR	COUNT
AMERICAN ENERGY UTICA LLC	3
CHESAPEAKE EXPLORATION LLC	1
CNX GAS COMPANY LLC	1
ECLIPSE RESOURCES I LP	1
EM ENERGY OHIO LLC	1
GULFPORT ENERGY CORPORATION	1
HESS OHIO RESOURCES LLC	3
PHILLIPS EXPLORATION INC.	1
PROTEGE ENERGY II LLC	1
STATOIL USA ONSHORE PROP INC.	14
TRIAD HUNTER LLC	13
XTO ENERGY INC.	3
TOTAL	43

Well permit information from the ODNR Division of Oil and Gas Resources Management

Recommended citation:

Ohio Department of Natural Resources, 2015, Horizontal Marcellus Well Activity in Ohio: Columbus, scale 1:1,300,000, revised 5/7/2015.

