


HORIZONTAL MARCELLUS WELL ACTIVITY IN OHIO



EXPLANATION

Horizontal well status as of 8/3/2019

- ◆ PERMITTED-(Permitted; Not Drilled; Canceled) (22)
- DRILLED-(Drilling; Well Drilled) (23)
- PRODUCING-(Producing; Plugged Back) (21)
- INACTIVE-(Drilled Inactive; Shut in) (2)
- Plugged and Abandoned (1)
- Other (1)

OPERATOR	COUNT
ALLIANCE PETROLEUM CORPORATION	1
ASCENT RESOURCES UTICA LLC	3
CNX GAS COMPANY LLC	1
EAP OHIO LLC	1
ECLIPSE RESOURCES I LP	23
EM ENERGY OHIO LLC	1
EQUINOR USA ONSHORE PROPERTIES INC.	15
HESS OHIO RESOURCES LLC	3
PHILLIPS EXPLORATION INC.	1
PROTEGE ENERGY II LLC	1
TRIAD HUNTER LLC	17
XTO ENERGY INC.	3
TOTAL	70



Well permit information from the ODNR Division of Oil and Gas Resources Management

Recommended citation:

Ohio Department of Natural Resources, 2019, Horizontal Marcellus Well Activity in Ohio: Columbus, scale 1:1,300,000, revised 8/5/2019.