


HORIZONTAL UTICA - PT PLEASANT WELL ACTIVITY IN OHIO



EXPLANATION

Horizontal well status as of 10/1/2016

- ◆ PERMITTED-(Permitted; Not Drilled; Canceled) (451)
- DRILLED-(Drilling; Well Drilled) (319)
- PRODUCING-(Producing; Plugged Back) (1,405)
- INACTIVE-(Drilled Inactive; Shut in) (44)
- Lost Hole or Final Restoration (33)
- Dry and Abandoned (3)
- Plugged and Abandoned (3)

Well permit information from the ODNR Division of Oil and Gas Resources Management

Recommended citation:

Ohio Department of Natural Resources, 2016, Horizontal Utica-Point Pleasant Well Activity in Ohio: Columbus, scale 1:1,300,000, revised 10/3/2016.

